

HISTORIC AMERICAN ENGINEERING RECORD

HAER  
DEL  
2-DELAC.V,  
1A-

INDEX TO PHOTOGRAPHS

FORT DELAWARE, SEA WALL  
Pea Patch Island  
Delaware City Vicinity  
New Castle County  
Delaware

HAER No. DE-56-A

Photographer: Michael Swanda, U.S. Army Corps of Engineers

October 1998

DE-56-A-1 NORTHWEST OBLIQUE AERIAL VIEW OF FORT DELAWARE AND PEA PATCH ISLAND. REMAINS OF SEA WALL VISIBLE IN FOREGROUND AND RIGHT OF IMAGE.

Photographer: Dawn A. Turner, Hunter Research, Inc.

March-April 1999

DE-56-A-2 NORTHEAST VIEW LOOKING ACROSS ERODED EASTERN CORNER OF SEA WALL. BUILDING FOUNDATION REMAINS IN FOREGROUND.

DE-56-A-3 SOUTH VIEW LOOKING ACROSS ERODED EASTERN CORNER OF SEA WALL. BUILDING FOUNDATION REMAINS IN FOREGROUND.

DE-56-A-4 EAST VIEW OF HEAVILY DETERIORATED SECTION OF SEA WALL LOOKING ACROSS ERODED EASTERN CORNER OF PEA PATCH ISLAND. BUILDING FOUNDATION REMAINS IN FOREGROUND.

DE-56-A-5 SOUTHEAST VIEW OF HEAVILY DETERIORATED INNER FACING OF NORTHEASTERN LEG OF SEA WALL.

DE-56-A-6 NORTHWEST VIEW OF EXPOSED GRILLAGE AT WESTERN EDGE OF SOUTHEASTERN LEG OF SEAWALL. FORT DELAWARE IN BACKGROUND.

DE-56-A-7 NORTHWEST VIEW OF GRILLAGE. SOUTHEASTERN LEG OF SEA WALL IN BACKGROUND.

DE-56-A-8 DETAIL OF NOTCHED CONSTRUCTION ELEMENT IN GRILLAGE AT WESTERN EDGE OF SOUTHEASTERN LEG OF SEA WALL. TIDE APPROACHING.

DE-56-A-9 SOUTH VIEW OF EXPOSED GRILLAGE AT NORTHEASTERN END OF SOUTHEASTERN LEG OF SEA WALL.

FORT DELAWARE SEA WALL  
HAER NO. DE-56-A  
Index to Photographs  
(Page 2)

- DE-56-A-10 NORTHWEST VIEW OF EXPOSED GRILLAGE AT NORTHEASTERN END OF SOUTHEASTERN LEG OF SEA WALL. SOUTHERN END OF NORTHEASTERN LEG OF SEA WALL IN BACKGROUND.
- DE-56-A-11 NORTH VIEW OF INNER FACING OF SOUTHEASTERN LEG OF SEA WALL. SOUTHERN END OF NORTHEASTERN LEG OF SEA WALL IN BACKGROUND.
- DE-56-A-12 NORTHEAST VIEW OF INNER FACING OF SOUTHEASTERN LEG OF SEA WALL. OBLIQUE ANGLE.
- DE-56-A-13 NORTHEAST VIEW OF INNER FACING OF SOUTHEASTERN LEG OF SEA WALL.
- DE-56-A-14 DETAIL OF STONWORK, INNER FACING OF SOUTHEASTERN LEG OF SEA WALL. VIEW EAST.
- DE-56-A-15 DETAIL OF CONSTRUCTION SHOWING IRON STRAPS, INNER FACING SOUTHEASTERN LEG OF SEA WALL.

FORT DELAWARE, SEA WALL  
HAER No. DE-56-A  
Key to Photographs  
(Page 3)

